THERM-cert range Product data sheet





+44 (0)1946 816600



brannan.co.uk

PRE-CALIBRATED TWIN THERMOMETER & HUMIDITY METER

High accuracy thermometer pre-calibrated at two fixed temperature points and part of the Brannan **THERM**-cert range.

White moulded case with two displays for temperature and humidity.

Product functions:

- · High accuracy thermometer supplied with traceable calibration certificate
- · Temperature and humidity reading
- · Max min readings with automatic reset
- · Large colour LCD
- · Easy reading comfort symbol
- · Celsius and Fahrenheit switchable
- · Hanging hook and desk stand
- · Battery included

Product specifications:

Temperature range: -10 to +50°C&F

Temperature accuracy: +/-1°C between 0 and 40°C, otherwise +/-2°C

Humidity range: 10 to 90% RH

Humidity accuracy: +/- 5%RH between 30 & 60%RH, otherwise +/-8%RH

Resolution: 0.1°C / 1%RH

Measurement update: Every 10 seconds

Max min auto reset: After 24 hours

Battery: 1pc x AAA or equivalent (included)

CE/ROHS/WEEE: Compliant

Hazard information (SDS): See brannan.co.uk for information

Product material: ABS

LCD dimensions: 73mm x 53mm

Product dimensions: Net: 94mm x 74mm x 19.5mm

Gross: 275mm x 240mm x 33mm

Weight: Net: 74.5g

Box & instructions: 14.5g

Gross: 105g (incl. certificate and packaging)



	ISSUED BY : S	Brannan and Sons Lim	ited	
CALIBRATION DATE		TIFICATE NUMBER	SERIAL NUMBE	
S. Brannan and Sonds Ltd. Leconfield Industrial Estate Cleater Moor Cumbria ENGLAND CA26 6QE		Brannan Thermometers and Gauges	Telephone: Fax: 4 Mail: sale 1: we Received No: 2	14 (0) 15 (154 19448144 19 (1947) 16 (194 19 (1947) 16 (194 1945) 12 (1947) 18
Instrument Type:	TWIN THERMON	EER UMIL VAR		
Range:	-10/50°C8F			
Resolution:	0.1°C	. 177		
Immersion:	egm .	\		
0.1	°C 0.0	*C N/A	246801/1	246801/
34.9	35.0	N/A	246801/1	246801/
Signed: Share	Cal	ibration Assistant and Approved Sig	natory	LIVES S
S. Moran Laboratory Temperature 201		Laboratory Humidity 20%		19

Description	Calibration points	Product no
THERM-cert pre-calibrated twin	2 fixed points at	TC-018
thermometer and humidity meter	0 and 35°C	



